ATC-1000S Upgrade

dministrator	S	System Status				
Authentication Configuration System IP Configuration	Ke	Kernel Version		V1. 44. 3. 1	. 10 2017/06/29	
	M	Address		00:11:22:54:95:7D		
System Status	N	ckname		NetUART	Update	
Load default	Ne					
Firmware update)	Comment name o	only can use "	0-9", "a-z"	,″A-Z″,″_″,″-″	
Boot Loader	选择此选	项进行固件升级				
TCP Mode	Salact	this option to	ungrado th	o firmwa	uro.	
UDP Mode	Jelect		upgraue th	CIIIIIwa	ne.	
UART						
SMTP						
ADC						
DIDO						
Reset Device						
63						
Idministrator			Firmwar	e Update		
Authentication		Please input the	nassword to cont	inue the Fir	mware Undate process	
Configuration		Password	•••••	.inde the Fill		
<u>Svstem IP</u> <u>Configuration</u>		ReConfirm			款K密码定system	
System Status			Upd	late		
Load default	Notice: After cli	cking the "UPDATE" but	tton, if the firm	ware update v	webpage is not redirected correctly	
Firmware update	or is sho	wn as "Webpagenot four	nd".			
Boot Loader	Tiease co	infect to http://192.10	56. 1. 150			
upgrade TCP Mode						
UDP Mode						
IIART						

Then will appear the Erase Flash interface:

Erase Flash (64/128) If this webpage doesn't refresh smoothly, please connect to <u>http://192.168.1.190</u> to continue.

	F/W	
Select the image file:	() 浏览。	Find the upgrade file: flash_512.bin
UPDATE		
<u>http://192.168.1.190</u>	点击浏览,找到	升级文件,
	.bin属性的文件	

flash_1M.bin	2017/6/29 星期	KuaiZipMount.bin	1,024 KB
flash_2M.bin	2017/6/29 星期	KuaiZipMount.bin	2,048 KB
flash_512.bin	2017/6/29 星期	KuaiZipMount.bin	512 KB
flash_app.bin	2017/6/29 星期	KuaiZipMount.bin	512 KB
OTP_64k.bin	2017/6/29 星期	KuaiZipMount.bin	64 KB
OTP_CLI_64k.bin	2017/6/29 星期	KuaiZipMount.bin	64 KB

F/W	
Select the image file: D:\文件备份\F盘\Support\ATC-1000问题\exe ATC Net-	-UART144.3.10 浏览
UPDATE b)	Click the update button

出现Uploading>>>表示正在升级 Uploading In progress...

2

OK!

Continue

升级完成点击 Continue 即可。Click Continue to complete the upgrade.

固件升级之后会重新跳出登录窗口,内部设置参数不会恢复出厂默认设置。

After the firmware upgrade, the login window will jump back, and the internal settings parameters will not revert to the factory default settings.