

## How to install Weintek USB driver

---

MT6000/8000 i series support the function of using a USB to Mini USB cable to download/upload projects from PC. It is necessary to install USB driver of HMI on PC before at the first time using this function.

1. Using USB cable mini side plug to HMI and another side plug into PC. The PC will display "Found New Hardware Wizard" dialog. Select "No, not this time" and click "Next".




2. Select "Install from a list or specific location (Advanced)" and click "Next".




3. Check "Include this location in the search", and assign the path to C:\EB8000

usbdriver, and click **Next**.



4. After that, it will automatic install Weintek HMI i Series driver from C:\EB8000\usbdriver.



5. After successful installation, click **Finish** button.



6. User can go Computer Management / Device Manager to check if the Weintek HMI i Series successfully be installed.

