


Error Message (0xc0000005)

When executing EB8000.exe, if an error message appears as below, please check if AVAST ANTIVIRUS software is installed on your PC.



AVAST ANTIVIRUS software of program version 5.1.889 or later has a possibility to conflict with EB8000 software and cause failure in EB8000 execution. To deal with this, please pause AVAST ANTIVIRUS software or remove it from your PC.

